

ELECTRICAL SAFETY RECALL

Automatic Submersible Vortex Pump

Wilo STV 180F-EM-A



IDENTIFICATION:

The product does not comply with the relevant mandatory electrical safety standard.

The cable in the flexible cord and earthing conductor supplied may have a defective earth core.

The product was sold nationally in Australia between 1 January 2015 and 25 September 2020.

HAZARD:

Risk of electric shock or electrocution.

ACTION REQUIRED:

Customers should disconnect and stop using the pump immediately. Affected consumers should contact Wilo Australia for advice on returning the product to arrange a full refund.

For further information

Please direct all calls and any queries concerning this recall to
Phone: 07 3907 6900 Or via Email Address: Recall.AU@Wilo.com

See www.productsafety.gov.au for Australian product recall information